



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No. 0247.68125
Replacement Sheet 1 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 1



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No. 0247.68125
Replacement Sheet 2 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 2



THERMOSTATIC MIXING VALVE
 Nicholas John Beck
 Greer, Burns & Crain, Ltd.
 Ref. No. 0247.68125
 Replacement Sheet 3 of 20

Serial No. 10/607,025
 Filed: June 26, 2003
 (Lawrence J. Crain)
 (312) 360-0080




Fig. 3



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No. 0247.68125
Replacement Sheet 4 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 4



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No. 0247.68125
Replacement Sheet 6 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 5



THERMOSTATIC MIXING VALVE
 Nicholas John Beck
 Greer, Burns & Crain, Ltd.
 Ref. No. 0247.68125
 Replacement Sheet 6 of 20

Serial No. 10/607,025
 Filed: June 26, 2003
 (Lawrence J. Crain)
 (312) 360-0080




Fig. 6




Fig. 7



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No. 0247.68125
Replacement Sheet 8 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 8



THERMOSTATIC MIXING VALVE
 Nicholas John Beck
 Greer, Burns & Crain, Ltd.
 Ref. No. 0247.68125
 Replacement Sheet 9 of 20

Serial No. 10/607,025
 Filed: June 26, 2003
 (Lawrence J. Crain)
 (312) 360-0080




Fig. 9




Fig. 10




Fig. 11



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No. 0247.68125
Replacement Sheet 12 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 12



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No. 0247.68125
Replacement Sheet 13 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 13



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No. 0247.68125
Replacement Sheet 14 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 14



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No.0247.68125
Replacement Sheet 15 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 15




Fig. 16



THERMOSTATIC MIXING VALVE
Nicholas John Beck
Greer, Burns & Crain, Ltd.
Ref. No. 0247.68125
Replacement Sheet 17 of 20

Serial No. 10/607,025
Filed: June 26, 2003
(Lawrence J. Crain)
(312) 360-0080




Fig. 17




Fig. 18




Fig. 19




Fig. 20